

GOOD & MAL-PRACTICES

This bulletin aims to present poor and good practices supported by photographic material.

EHSEC hopes that this material be used for reference in training sessions or for benchmarking purposes.

EHSEC also urges all members to contribute with relevant material as long as the material:

- Was legally obtained
- The photograph does not reveal the identity of workers by showing their faces.
- The photograph does not reveal the identity of the company depicted.
- The photograph does not reveal the identity of any brand name.
- Is not protected by copyright issues

All rights for the pictures contained in this bulletin are protected.

Good Practice



Car exhausts are connected to a dedicated central exhaust system in order not to emit the exhaust gases in the area.

Malpractice



Same car maintenance shop: Food and drinks are allowed during maintenance; this is a poor practice violating the basic hygiene rules; smoking is not allowed but the smoking gear are present.

Malpractice



Grinding wheels with the protective covers removed.

Malpractice



Storage of combustible materials (in this case flammable) under a staircase, not to mention the installation of a Fire Hose as well as other fire-fighting equipment in a semi-accessible area.

Good Practice



Well demarcated fluid-flow lines that facilitate identification as well as safe maintenance since it makes line-breaking easier and quicker to apply.

Good Practice



Boiler room housekeeping; note again the line demarcation.